



Rai_Fix System



1 Bracket 01	6 Vertical profile (T/L Profile)
2 Bracket 02	7 Rai_Fix
3 Polyurethane insulation	8 Self drilling screw 02
4 Anchor	9 Cladding
5 Self drilling screw 01	

 www.juangroup-lb.com Lb: +961 70 020 332, CM: +237 6 78 09 99 99 BJ: +229 5 129 99 99, CI: +225 0 799 553 311 SN: +221 781 529 191, UAE: +971 52 710 4804	Substructure system	Rai_Fix System Attica section	Plan-Nr. drawing no. Rai_Fix 01
	Description		

Rai_Fix System



1 Bracket 01	6 Vertical profile (T/L Profile)
2 Bracket 02	7 Rai_Fix
3 Polyurethane insulation	8 Self drilling screw 02
4 Anchor	9 Cladding
5 Self drilling screw 01	



Lb: +961 70 020 332, CM: +237 6 78 09 99 99
 BJ: +229 5 129 99 99, CI: +225 0 799 553 311
 SN: +221 781 529 191, UAE: +971 52 710 4804

Substructure system


Rai_Fix System
intel detail

Description

Plan-Nr. | drawing no.

Rai_Fix 02

Rai_Fix System



1 Bracket 01	6 Vertical profile (T/L Profile)
2 Bracket 02	7 Rai_Fix
3 Polyurethane insulation	8 Self drilling screw 02
4 Anchor	9 Cladding
5 Self drilling screw 01	



Lb: +961 70 020 332, CM: +237 6 78 09 99 99
 BJ: +229 5 129 99 99, CI: +225 0 799 553 311
 SN: +221 781 529 191, UAE: +971 52 710 4804

Substructure system

Rai_Fix System


Description

Window sill detail

Plan-Nr. | drawing no.

Rai_Fix 03

Rai_Fix System



1 Bracket 01	6 Vertical profile (T/L Profile)
2 Bracket 02	7 Rai_Fix
3 Polyurethane insulation	8 Self drilling screw 02
4 Anchor	9 Cladding
5 Self drilling screw 01	



Lb: +961 70 020 332, CM: +237 6 78 09 99 99
 BJ: +229 5 129 99 99, CI: +225 0 799 553 311
 SN: +221 781 529 191, UAE: +971 52 710 4804

Substructure system

Rai_Fix System


Description

Vertical section

Plan-Nr. | drawing no.

Rai_Fix 04

Rai_Fix System



1 Bracket 01	6 Vertical profile (T/L Profile)
2 Bracket 02	7 Rai_Fix
3 Polyurethane insulation	8 Self drilling screw 02
4 Anchor	9 Cladding
5 Self drilling screw 01	10 Metal net



Lb: +961 70 020 332, CM: +237 6 78 09 99 99
 BJ: +229 5 129 99 99, CI: +225 0 799 553 311
 SN: +221 781 529 191, UAE: +971 52 710 4804

Substructure system

Rai_Fix System


Description

Plinth detail

Plan-Nr. | drawing no.

Rai_Fix 05

Rai_Fix System



1 Bracket (01/02)	6 Vertical profile (T/L Profile)
2	7 Rai_Fix
3 Polyurethane insulation	8 Self drilling screw 02
4 Anchor	9 Cladding
5 Self drilling screw 01	



Lb: +961 70 020 332, CM: +237 6 78 09 99 99
BJ: +229 5 129 99 99, CI: +225 0 799 553 311
SN: +221 781 529 191, UAE: +971 52 710 4804

Substructure system

Rai_Fix System


Description
1. The first row of the table is the header row, which contains the column names: "Description", "Amount", "Date", and "Category".
2. The second row of the table is the first data row, which contains the values: "Groceries", "150.00", "2023-10-01", and "Food".
3. The third row of the table is the second data row, which contains the values: "Utilities", "75.00", "2023-10-05", and "Bills".
4. The fourth row of the table is the third data row, which contains the values: "Salary", "1200.00", "2023-10-10", and "Income".
5. The fifth row of the table is the fourth data row, which contains the values: "Rent", "900.00", "2023-10-15", and "Housing".
6. The sixth row of the table is the fifth data row, which contains the values: "Transportation", "30.00", "2023-10-20", and "Travel".
7. The seventh row of the table is the sixth data row, which contains the values: "Entertainment", "50.00", "2023-10-25", and "Hobbies".
8. The eighth row of the table is the seventh data row, which contains the values: "Savings", "200.00", "2023-10-30", and "Investment".
9. The ninth row of the table is the eighth data row, which contains the values: "Total", "1505.00", "2023-10-31", and "Summary".

Horizontal section

Plan-Nr. | drawing no.


Rai_Fix 06

Rai_Fix System




1 Bracket (01/02)	6 Vertical profile (T/L Profile)
2	7 Rai_Fix
3 Polyurethane insulation	8 Self drilling screw 02
4 Anchor	9 Cladding
5 Self drilling screw 01	
 www.juangroup-lb.com Lb: +961 70 020 332, CM: +237 6 78 09 99 99 BJ: +229 5 129 99 99, CI: +225 0 799 553 311 SN: +221 781 529 191, UAE: +971 52 710 4804 Substructure system Rai_Fix System Description inside corner Plan-Nr. drawing no. Rai_Fix 07	

Rai_Fix System



1 Bracket 01	6 Vertical profile (T/L Profile)
2 Bracket 02	7 Rai_Fix
3 Polyurethane insulation	8 Self drilling screw 02
4 Anchor	9 Cladding
5 Self drilling screw 01	
 www.juangroup-lb.com Lb: +961 70 020 332, CM: +237 6 78 09 99 99 BJ: +229 5 129 99 99, CI: +225 0 799 553 311 SN: +221 781 529 191, UAE: +971 52 710 4804 Substructure system Rai_Fix System Description outside corner Plan-Nr. drawing no. Rai_Fix 08	

Rai_Fix System



1 Bracket (01/02)	6 Vertical profile (T/L Profile)
2 Vertical profile (click profile 02)	7 Rai_Fix
3 Polyurethane insulation	8 Self drilling screw 02
4 Anchor	9 Cladding
5 Self drilling screw 01	



Lb: +961 70 020 332, CM: +237 6 78 09 99 99
 BJ: +229 5 129 99 99, CI: +225 0 799 553 311
 SN: +221 781 529 191, UAE: +971 52 710 4804

Substructure system

Rai_Fix System

Description

reveal detail

Plan-Nr. | drawing no.

Rai_Fix 09